Warranty Vehicle Inquiry

Sat Apr 09 15:36:38 EDT 2011

PD97639 CONFIDENTIAL

THIS DOCUMENT IS NOT TO BE USED OR RELIED UPON FOR IMPORT OR EXPORT PURPOSES AND IS NOT TO BE DISTRIBUTED OR SHARED WITH THIRD PARTIES*

*EXCEPT FOR SPECIFIC INFORMATION THAT MAY BE REQUIRED BY LAW

DO NOT USE DAVIS AS THE SOLE INDICATOR FOR CALCULATING VEHICLES' DAYS OUT OF SERVICE. DAVIS IS A GUIDE ONLY AND DOES NOT INCLUDE EXACT NUMBERS AS CONFLICTS IN DAYS TO CLOSE A REPAIR ORDER MAY EXIST.

© 2011 BMW of North America, LLC

| Vehicle Data | | | | | | |
|---|--|--|--|--|--|--|
| VIN: WBABD53484PD97639 | Davis #: N/A | | | | | |
| Chassis Number: PD97639 | Assist Safety Plan Expires: 00/00/0000 | | | | | |
| Line Make: 01 - BMW | Assist Conv. Plan Expires: 00/00/0000 | | | | | |
| Model Year: 2004 | TCU ESN / TCU IMEI: 14602263617 INACTIVE | | | | | |
| AG Model Code/Desc: BD53 - 330Cl | TCU MIN: XXX-XXX-XXXX | | | | | |
| NA Model Code/Desc: 0433 - 330Ci | MDN / MSISDN: XXX-XXX-XXXX | | | | | |
| Interior Trim Code: N6SW - Black Leather | Vehicle Production Date: 2004/03 | | | | | |
| Exterior Color Code: A08 - Silver Gray Metallic | Motor Type: M54 | | | | | |
| MSRP: \$46,670.00 | Platform/Engineering Series: E46 | | | | | |
| | Wholesale Center ID/Loc: 22900-01 | | | | | |
| | Wholesale Date: 05/22/2004 | | | | | |
| | Retail Center ID/Loc: 86716-01 | | | | | |
| | Retail Date: 06/23/2004 | | | | | |
| | In-Service Date: 06/23/2004 | | | | | |

New Vehicle Warranty Info

No Coverage As Of: 06/23/2008

Expiration Mileage: 50,000

NO OPEN CAMPAIGNS

| Option Information | | | | | | | |
|--------------------|-------------|------|-------------|--|--|--|--|
| Code | Description | Code | Description | | | | |

Chassis Number : PD97639

| 0ZCW | Cold Weather Package | 0ZHP | Performance Package |
|------|--------------------------------|------|---------------------------|
| 01CA | CO2 relevant vehicles | 0403 | Moonroof |
| 0441 | Smoker's package | 0459 | Power front seats |
| 0521 | Rain sensor and auto headlight | 0522 | Xenon headlights |
| 0524 | Adaptive light control | 0534 | Automatic climate control |
| 0639 | BMW Assist with Bluetooth | 0650 | In-dash CD player |
| 0674 | Harman-Kardon sound system | 0692 | CD changer preparation |
| 08SP | CO2 control | 0818 | Battery switch |

Customer Information

Name (First/Last):

Adderss:

| Contrac | Contract/Service Program Information | | | | | | | | | | |
|---------|--------------------------------------|---------------------------|------------|------------|-------------------------|----|----------------------------|-------|-------------|----|---------------------------------|
| Туре | Program Code/Desc | Contract Number/Status | | Date | No Coverage As Of | | Exp Odometer (Miles) | | | | Contract Holder (First/Last) |
| MP | 0000000168 - MP 48 MO/050K MLS | 0000000 EXPIRED | 06/23/2004 | 06/23/2004 | 06/23/2008 | 48 | 50,000 | 86716 | Patrick BMW | MP | |
| СРО | 0000000005 - CPO 72 MO/100K MLS | 0000000 EXPIRED | 06/23/2004 | 05/24/2007 | 06/23/2010 | 72 | 100,000 | 86716 | Patrick BMW | UW | |

| ELIGIBLE Contract/Service Program Information (Optional programs only, CPO eligibility not provided) | | | | | | | | | |
|--|---|-----------------|---------|------------|---------------------|--|--|--|--|
| Туре | Program Code/Desc | Wholesale Price | MSRP | Deductible | Vendor Code Used | | | | |
| ESC | 000000061 - ESC USED PT+ 12M/12K MIs | N/A | 1670.00 | 50.00 | PT | | | | |
| Disclaimer: | The Eligible Contract indicators do not necessarily mean that the vehicle/vehicle owner is currently eligible for the indicated contracts. The Eligible Contract indicators are only suggestions to the dealer, based on the latest data to which BMW has access about the vehicle. For actual enrollment of the vehicle in any of the optional programs, please use the Vehicle Contract System. | | | | | | | | |

| Repair History (Claims) | | | | | | | | | | | |
|-------------------------|----------------|-----------------|------------|-------------------|----------------------|----------------------|---------|---------|----------------|----------------------|--------------------------|
| Center ID | Location ID | Claim Number | | Repair Order # | Repair Order Date | Repair Entry Date | Davis # | Mileage | Defect Code | Description | |
| 86716 | 01 | 117429 | 07/05/2008 | 354643 | 07/03/2008 | 07/05/2008 | N/A | 71,097 | 99999977U W | HANDLING CHARGE UCPP | \$50.00 PER REPAIR VISIT |

Page : 2

THIS DOCUMENT IS NOT TO BE USED OR RELIED UPON FOR IMPORT OR EXPORT PURPOSES AND IS NOT TO BE DISTRIBUTED OR SHARED WITH THIRD PARTIES*

*EXCEPT FOR SPECIFIC INFORMATION THAT MAY BE REQUIRED BY LAW

DO NOT USE DAVIS AS THE SOLE INDICATOR FOR CALCULATING VEHICLES' DAYS OUT OF SERVICE. DAVIS IS A GUIDE ONLY AND DOES NOT INCLUDE EXACT NUMBERS AS CONFLICTS IN DAYS TO CLOSE A REPAIR ORDER MAY EXIST. © 2011 BMW of North America, LLC

Chassis Number : PD97639

| Center ID | Location ID | Claim Number | Claim Date | Repair Order # | Repair Order Date | Repair Entry Date | Davis # | Mileage | Defect Code Description |
|--------------|----------------|-----------------|------------|-------------------|----------------------|----------------------|---------|---------|--|
| 86716 | 01 | 117420 | 07/05/2008 | 354643 | 07/03/2008 | 07/05/2008 | N/A | 71,097 | 11612112U INTAKE MANIFOLD SOLENOID VALVE FAILED W |
| 86716 | 01 | 402830 | 06/26/2007 | 325479 | 06/22/2007 | 06/26/2007 | N/A | 50,256 | 32330668SA STEERING WHEEL COVER PEELS OFF / DETACHES ITSELF |
| 86716 | 01 | 395690 | 06/07/2007 | 323265 | 06/01/2007 | 06/07/2007 | N/A | 49,603 | 6166034000 Windshield washer system, spray nozzles poorly adjusted / outside tolerance |
| 86716 | 01 | 334410 | 01/12/2007 | 313289 | 01/09/2007 | 01/12/2007 | N/A | 49,265 | 5121002900Rotary latch lock/system lock, front sticking/jammed5172004100Edge protector (door aperture) poorly adapted/fitted61610077MPFT WIPER RUBBER INSERT-MP |
| 86716 | 01 | 236810 | 05/19/2006 | 295964 | 05/16/2006 | 05/19/2006 | N/A | 45,130 | 34000077MPBRAKE FLUID CHANGE- FULL MAINTENANCE PROGRAM34117777MPFRONT BRAKE PADS & ROTORS - MAINTENANCE PLAN34210077MPRR BRAKE PADS - MAINTENANCE PLAN5412053700Floating headliner / roller blind loose61610077MPFT WIPER RUBBER INSERT-MP85990091MPOIL SERVICE(MP)AFTER THE 1ST |
| 86716 | 01 | 162850 | 11/12/2005 | 282669 | 11/09/2005 | 11/12/2005 | N/A | 31,322 | 0012100200 SIB #12-13-05 RECALL 05E-A01 BREMI IGN COILS REPLACEMENT 1214151100 Component, DME control unit occasional failure |
| 86716 | 01 | 154270 | 10/25/2005 | 281142 | 10/20/2005 | 10/25/2005 | N/A | 30,042 | 11009999SA BMW NA RENTAL COST - GOODWILL 61610077MP FT WIPER RUBBER INSERT-MP 85990092MP INSPECTION 1 (MP) |
| 86716 | 01 | 128980 | 08/17/2005 | 276289 | 08/12/2005 | 08/17/2005 | N/A | 24,766 | 5172003700 Edge protector (door aperture) loose |
| 86716 | 01 | 67940 | 03/05/2005 | 264380 | 03/03/2005 | 03/05/2005 | N/A | 14,917 | 3400045600 Front axle brakes - vibration poor running characteristics / friction |
| 86716 | 01 | 64670 | 02/24/2005 | 263912 | 02/22/2005 | 02/24/2005 | N/A | 14,403 | 5121006500 Rotary latch lock/system lock, front does not lock into position 5131000700 Windshield cracked 85990089MP 1ST ENG OIL SERVICE-FULL MAINTENANCE |
| 96311 | 01 | 153130 | 05/28/2004 | 228992 | 05/21/2004 | 05/28/2004 | N/A | 5 | 9999010100 Missing parts ex factory |

Page : 3

THIS DOCUMENT IS NOT TO BE USED OR RELIED UPON FOR IMPORT OR EXPORT PURPOSES AND IS NOT TO BE DISTRIBUTED OR SHARED WITH THIRD PARTIES*

*EXCEPT FOR SPECIFIC INFORMATION THAT MAY BE REQUIRED BY LAW

DO NOT USE DAVIS AS THE SOLE INDICATOR FOR CALCULATING VEHICLES' DAYS OUT OF SERVICE. DAVIS IS A GUIDE ONLY AND DOES NOT INCLUDE EXACT NUMBERS AS CONFLICTS IN DAYS TO CLOSE A REPAIR ORDER MAY EXIST. © 2011 BMW of North America, LLC